Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight — ***DHR Id#:*** **046-5077**

Resource Identification

Property Name(s): ..... Fortune House {Descriptive}
Property Date: ..... ca 1918
Address(s): ..... 18564 Route 649 {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... RAYNCR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior end	Brick	Chimneys - Common Bond
Foundation	Foundation - Piers	Brick	Foundation - Common Bond
Porch	Porch - 1-story, 3-bay	Wood	Porch - Post, Square
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Vinyl	Structural System - Vinyl Siding
Windows	Windows - Sash, double-hung	Aluminum	Windows - [illegible]
Chimneys	Chimneys - Exterior end	Brick	Chimneys - Common Bond

Site Description: ..... This house is located in a rural area in Isle of Wight County.

Secondary Resource Desc: There are four outbuildings associated with this house.

WUZIT Count.

No.	Wuzit Types	Historic?
2	Shed	Historic
1	Equipment Shed	Historic
1	Garage	Historic
1	House	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5077**

Individual Resource Information

WUZiT: Shed

Est. Date of Construction:	1920 ca	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Shed (B) is a small weatherboard covered structure with a gabled roof clad in standing-seam metal

WUZiT: House

Est. Date of Construction:	1918 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	2.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Built c. 1918, this two-story I-House features a wooden frame structural system that rests on brick piers. The exterior is covered in vinyl siding and the hipped roof with flared eaves is clad in standing-seam metal. This house features three brick chimneys. Fenestration consists of new one-over-one aluminum double-hung sash windows. A hipped addition has been appended to the north façade and the south façade features a hipped porch with chamfered posts.

WUZiT: Shed

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: East of the house are four outbuildings. Shed (A) and the garage both feature gabled roofs and are completely clad in standing-seam metal.

WUZiT: Garage

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: East of the house are four outbuildings. Shed (A) and the garage both feature gabled roofs and are completely clad in standing-seam metal.

WUZiT: Equipment Shed

Est. Date of Construction:	1920 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: East of the house are four outbuildings. The equipment shed is covered in corrugated metal and displays a gabled roof clad in standing-seam metal.

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5077**

Historic Context(s): ..... Domestic
Subsistence/Agriculture

Historic Time Period(s): ..... R- World War I to Present (1914 - Present)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Reference #: 1
Bibliographic RecordType: ..... Survey
Author: ..... CCR, Inc
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Name: ..... Unknown Fortune
Zip: ..... *State:* Georgia *Country:*

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	6	VDHR	2004/07/06	Farm Complex

Cultural Resource Management (CRM) Events

CRM Event # 1.
Cultural Resource Management Event: ..... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2.
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: .....